## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s):	Ulmer/R	Date(s):	5-8 Aug 2019	
Company (Orange)			Linit (ODID)	0160
Company/Owner:	Intermot	untain Gas Company	Unit/OPID:	8160
Inspection Type & Time (	4 day, 0.5 day)	Total	Inspection Days:	8.5
Standard: Construction	n: 8.5 Training:	(T)(D) Integrity Managemen	t: Incident:	
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on KV Utilities, a contractor for Intermountain Gas Company.				
5-8 Aug 2019: (8.0 Construction) Observed the crew potholing in preparation for the bore. They excavated the 2" PE they had split/pulled prior to our inspection. Watched a "Missile/thumper" shot for a section of the 2" PE main installation. Watched them bore on the main road to their tie-in location. They were stopped short due to the rocky ground and had to trench the rest to the tie-in location. They pulled back the 2" main for they section of bore the had completed.				
Areas observed during this project were: Trenching, Boring, Squeezing, Mechanical coupling, Line Locating  9 Aug 2019: (.5 post Construction)  Type construction report.				
Attachments:				
IPUC Form 4 Construction Inspections				
KV Utilities Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.				
Corrective Action Required	Follo	ow-up Required:	'es No	Х
	o X //		by (date):	
Inspector (Lead):	J .#/	YHENN II	Date:	
Darrin Ulmer	Ware			7 Aug 2019
Reviewer:			Date:	